



USCG MSU Hou/Gal
Port Freeport Users

August 25, 2014

Re: Anchorage area obstruction

To whom it concerns,

On August 25, 2014 one of our inbound vessels came off anchor from the north Freeport general anchorage. While heaving the anchor, it was determined that a 1 1/8' to 1 1/4' wire was fouled in the anchor. The wire was cut and the vessel was able to proceed to berth.

The obstruction continues to exist in Lat 28° 53.691N, Long 095° 11.704W. The wire is estimated to be 600'-700' long, laying in a general east/west direction and constitutes a hazard to vessels anchoring in or near the above location.

Your effort in advising vessels to anchor clear of this area is greatly appreciated.

Regards,

A handwritten signature in cursive script that reads "James Teeter".

James Teeter
President